

## GEARCHANGE

### Subject: Gearchange clutch dogs

Model: Nevada 750

#### Problem:

the **3rd** and **4th** gears slip out.  
We highlighted two causes:

1. The circlips (**S**) doesn't keep the washer in place.
2. After inspecting the **3rd** and **4th** gears clutch dogs, it was noticed that the angle was not correct (should be **6°**) maybe due to wrong machining or because it was exchanged with one for the Brevia 750 gearchange.

#### Solution:

1. it was fitted the circlip for the Brevia gearchange (**inner diameter undersized by 0.5 mm part no. 90271124**).
2. Changing the gears that do not comply with the drawings.

**NOTE : the gear for the Nevada 750 gearchange is marked with number 6**

