ADDITIONAL TEL . WIE NUILLERS [201] 288 | 9696.7. 9694, 8968, 9063 [212] 736 3940-1

MOTO GUZZI

PREMIER Motor Corporation

RAILROAD STREET AND PLANT ROAD . HASBROUCK HEIGHTS, NEW JERSEY 07604 (201) 288-9694 - (212) 736-3940 · CABLE ADDRESS: PREMOTOR · TELEX: 138-002 EXCLUSIVE DISTRIBUTOR IN THE UNITED STATES AND CANADA

BULLETIN #46A

NATURE OF RELEASE:

Transmissions 13991560/3 and FLYWHEEL

BOLTS, 12067701 (10 K)

MODEL:

850 Eldorado

DISTRIBUTION:

ALL DEALERS

EXPLANATION:

It is apparent that some doubt exists regarding the changing of transmissions 13991560/3 and Flywheel Bolts 12067701 per Bulletin #46.

The bolts to check and change if necessary are the six bolts locating the flywheel to the crankshaft, and are not to be confused with the starter ring bolts which do not have to be changed.

The flywheel bolts must be marked lok. If they are not they must be changed when fitting replacement transmission.